A STATUTE OF PRODUCE ON PLANTA

21793 Wt. 38805/3593 400,000 12/39-McC & Co-51-5658

R.A.F. Form 540

See instructions for use of this form in K.R. and A.C.I., para. 2349, and War Manual, Pt. II., chapter XX., and notes in R.A.F. Pocket Book.

## OPERATIONS RECORD BOOK

HE MINT ON THE PROPERTY

Page No. 1.

of (Unit or Formation) No. 95 Squadror

No. of pages used for day\_\_\_

Place	Date	Time	Summary of Events	Referen- to Appendi
JII.	16,11,42		Four Sunderlands (DV. 973, DV. 975, T. 9078, DV. 964) returned from Bathurat two doing Alp North and two coastal reces. A small convoy was sighted.	01,02,0
	17.11.42	UP 0656 DOWN 1735 UP 0625	Sunderland IW. 964 C/95. A/S Patrol. Located and escorted U.S. Tanker "American Sun".	06
	17.11.42	DOWN 1630 UP 0655	Sunderland T.9078 4/95. Search for lifeboats, nothing sighted.	05
			Sunderland T. 9078 4/95. Search for Elockade Sunners, "Ammaliese Essberg" and "Kota Napan".	08
		IP 0655 DOWN 2050	Sunderland, DV.973 J/95. Search for Blockade Runners. Signted 2 M.V.s, "Manchester Division" and "Atlantic City".	07
		TP 0700 DOWN 1730	Sunderland DV. 964. C/95. Locate and escort "Bridgewater" and tug towing A.S.T. "Northern Isles". "Bridgewater" not located. Small convoy sighted.	02
	24.11.42		Sunderland IW.975 H/95. Search for suspicious vessel, which was located and identified as U.S. M/V. "Narbo".	03
	27.11.42	IP 0645 XXIII 1705 IP 0750	Sunderland DV.964 C/95. Recort convoy FTT.3.	04
	28.11.42		Sunderland DV.964 C/95. Escort convoy FTT.3.	05
	22.11.4.20		Sunderland DV.975 H/95. Flare dropping exercise with submarine and A/S Patrol.	01
	28.11.42	OWN 1805	Sunderland, DV. 975 H/95. Crashed in the river BUNCE off JUI after a D/F exercise with a H. S. L. F/Lt. Bocock, de K. P. H., F/Lt. Steer, J. R., P/O. Leech, R. L., and F/Lt. Webb-Jones, A. (M.O.), were injured and F/Sgt. Raylor, M. R., Sgt. Creatie, J. J., Sgt. Irvine, R., Sgt. Hogg, W.A., Sgt. Hadwell, C.W., Sgt. Searl, W.F., and F/Sgt. Robinson, R.W., were killed. The aircraft caught on fire. What remained of the aircraft after the fire, was later blown up since it was a danger to navigation.	
	(CO) 3			*
BEALS.		me za		
No.				2
	The state of the s			CONTRACTOR AND ADDRESS.

PUBLIC RECORD OFFICE 1 2 3 4 5 6

Reference:
AIR 27 -/ 761 1 2

COPYRIGHT - NOT TO BE REPRODUCED PHOTOGRAPHICALLY MYTHOUT PEINISSION